



Scheibenwischer  
Rennerliste



Wiper blades  
Bestseller's list



Щетки стеклоочистителей  
Список наиболее продаваемого ассортимента



Wycieraczki  
Lista najlepiej rotujących części



Ausgabe - Edition - Издание - Wydanie  
2008

[www.master-sport.de](http://www.master-sport.de)

<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>13"-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>330 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>DAEWOO</b> H</li> <li>• <b>DAIHATSU</b> Cuore (97-&gt;01) H ; Cuore (01-&gt;) H ; Sirion (98-&gt;) H ; Terios (97-&gt;) H</li> <li>• <b>FIAT</b> 126 (73-&gt;00) L ; Bravo (95-&gt;) H ; Panda (80-&gt;03) H ; Punto (93-&gt;00) H ; Seicento (98-&gt;) H ; Siena; Palio W. (97-&gt;) H ; Uno (83-&gt;) H</li> <li>• <b>FORD</b> Maverick (93-&gt;99) H ; Mondeo (93-&gt;01) com.H ; Sierra combi ( ) H</li> <li>• <b>GAZ</b> 3110, 3307, 4301 ; Gazel 3302 ( )</li> <li>• <b>HONDA</b> CR-V (97-&gt;) H</li> <li>• <b>HYUNDAI</b> Santa Fe (01-&gt;) H</li> <li>• <b>JEEP</b> Cherokee (88-&gt;) H</li> <li>• <b>LADA</b> 2101-2107 (81-&gt;) L ; Niva (76-&gt;94) L ; Niva (94-&gt;) H</li> <li>• <b>LANCIA</b> Y 10 (84-&gt;93) H</li> <li>• <b>MITSUBISHI</b> Space Star (98-&gt;) H</li> <li>• <b>NISSAN</b> Almera (00-&gt;) H</li> <li>• <b>OPEL</b> Agila (00-&gt;) H ; Kadett (84-&gt;91) H</li> <li>• <b>SEAT</b> Marbella (86-&gt;96) H</li> <li>• <b>SUBARU</b> Vivio (92-&gt;) H</li> <li>• <b>SUZUKI</b> Alto (86-&gt;94) H ; Alto (94-&gt;) H</li> <li>• <b>VOLVO</b> 960 (90-&gt;97) H</li> <li>• <b>VW</b> Golf III (91-&gt;97) H ; Golf IV (97-&gt;) H</li> <li>• <b>ZAZ</b> Tavria (88-&gt;) H</li> </ul>
<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>14"-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>350 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>CITROËN</b> H</li> <li>• <b>DAEWOO</b> Damas (00-&gt;) R ; Matiz (98-&gt;) H</li> <li>• <b>DAIHATSU</b> Charade (87-&gt;90) H ; Charade (90-&gt;) H ; Feroza (89-&gt;) H ; Terios (97-&gt;) R</li> <li>• <b>FIAT</b> Punto II (00-&gt;) H</li> <li>• <b>FORD</b> Escort (90-&gt;98) H</li> <li>• <b>HONDA</b> Stream (01-&gt;) R</li> <li>• <b>HYUNDAI</b> Atos (97-&gt;) H ; Galoper (98-&gt;) H ; H100/H350/H600 (94-&gt;00) ; Lantra / Elantra (95-&gt;) com.H</li> <li>• <b>KIA</b> Asia (94-&gt;99) L ; Carens (00-&gt;) H</li> <li>• <b>MAZDA</b> 323C / F / P / S (89-&gt;94) H ; 626 (87-&gt;91) H ; Premacy (99-&gt;) H</li> <li>• <b>MITSUBISHI</b> Colt / Mirage (88-&gt;95) H ; Colt / Mirage (95-&gt;) H ; Galoper (98-&gt;) H ; Space Wagon (91-&gt;) H</li> <li>• <b>NISSAN</b> Almera (95-&gt;00) H ; Primera (90-&gt;) com.H ; Sunny (90-&gt;) hatch.H</li> <li>• <b>OPEL</b> Combo (01-&gt;) H ; Corsa B (93-&gt;00) H ; Omega A (86-&gt;94) com.H ; Vectra B (95-&gt;02) com.H</li> <li>• <b>PEUGEOT</b> 405 (87-&gt;97) com.H ; 406 (96-&gt;) com.H ; Partner (96-&gt;) H</li> <li>• <b>RENAULT</b> Kangoo (97-&gt;) H ; Laguna I (94-&gt;01) com.H ; Megane (96-&gt;02) com.H</li> <li>• <b>ROVER</b> Discovery I (89-&gt;98) H</li> <li>• <b>SEAT</b> Ibiza (93-&gt;01) H</li> <li>• <b>SUZUKI</b> Carry (89-&gt;98) R ; Samurai (81-&gt;) H</li> <li>• <b>ŠKODA</b> Octavia (96-&gt;) com.H</li> <li>• <b>TOYOTA</b> Avensis (97-&gt;) com.H ; Camry (91-&gt;00) com.H ; Carina E (92-&gt;) com.H ; Corolla (87-&gt; 01) com.H ; Dyna (85-&gt;) H ; J7 (85-&gt;) H ; J8 (90-&gt;) H ; RAV 4 (94-&gt;00) H ; Yaris (99-&gt;) R</li> <li>• <b>VOLVO</b> 740, 760, 780 (83-&gt;95) H ; 940 (90-&gt;97) H ; S 90, V 90 (96-&gt;98) H</li> </ul>
<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>15"-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>380 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> H</li> <li>• <b>AUDI</b> A 3 (96-&gt;) H ; A 4 (94-&gt;99) com.H</li> <li>• <b>DAEWOO</b> Damas (00-&gt;) L ; Nubira (97-&gt;) H ; Tacuma (00-&gt;) H</li> <li>• <b>DAIHATSU</b> Applause (89-&gt;) H ; Cuore (97-&gt;01) R ; Move (95-&gt;98) R</li> <li>• <b>FIAT</b> Fiorino (80-&gt;88) L</li> <li>• <b>FORD</b> Focus (98-&gt;) com.H</li> <li>• <b>HONDA</b> Accord (89-&gt;) H ; Civic (83-&gt;87) H ; Civic Aerodeck (98-&gt;) H ; Civic / Type R (01-&gt;) R ; Shuttle (94-&gt;) H</li> <li>• <b>ISUZU</b> Trooper (92-&gt;) H</li> <li>• <b>KIA</b> Clarus (96-&gt;) com.H ; pride (90-&gt;01) H ; Rio (00-&gt;) H</li> <li>• <b>LADA</b> 2101-2107 L ; Niva (94-&gt;) L</li> <li>• <b>LANCIA</b> Thema (84-&gt;94) com.H</li> <li>• <b>MAZDA</b> 121 (87-&gt;91) H ; 121 (91-&gt;95) H</li> <li>• <b>MERCEDES</b> 200D-260E (W124) (84-&gt;96) com.H ; 200D-280E (W123) (76-&gt;85) com.H ; E Class (W210) (95-&gt;) com.H ; G (W463) (93-&gt;) H ; ML (W163) (97-&gt;) H</li> <li>• <b>MITSUBISHI</b> Pajero / Montero (90-&gt;00) H</li> <li>• <b>NISSAN</b> Bluebird (86-&gt;94) H ; Patrol GR (98-&gt;) H ; Primera (99-&gt;01) com.H ; Vanette (85-&gt;90) H ; Vanette (90-&gt;96) H ; X-Trail (01-&gt;) R</li> <li>• <b>OPEL</b> Monterey (92-&gt;) H</li> <li>• <b>PEUGEOT</b> Express (82-&gt;94) H</li> <li>• <b>RENAULT</b> R 5 (84-&gt;96) H</li> <li>• <b>ROVER</b> 100 (90-&gt;) H</li> <li>• <b>SUBARU</b> Forester (97-&gt;) H ; Impreza (92-&gt;) H ; Vivio (92-&gt;) R</li> <li>• <b>SUZUKI</b> Baleno (94-&gt;) H ; Carry (89-&gt;98) L ; Grand Vitara (98-&gt;) H ; Swift (84-&gt;89) H ; Vitara (89-&gt;) H</li> <li>• <b>VW</b> Passat (82-&gt;88) H ; Passat B5 (96-&gt;) H</li> </ul>

# 16" -PCS-MS

410 MM

- **ALFA ROMEO** L ; Alfa 147 (01->) R
- **AUDI** 80 / 90 (84->94) com.H
- **CITROËN** AX (86->) H ; CX (82->93) H ; Saxo (96->) H ; XM (94->) H
- **DAEWOO** Matiz (98->) R ; Polonez (78->94) L +H ; Tico (91->) R
- **DAIHATSU** Move (95->98) L ; Move (99->) R
- **FIAT** Panda (80->03) L ; Punto (93->00) R ; Regata (83->90) L
- **FORD** Fiesta (83->89) L+H ; Fiesta (89->) H ; Fiesta (02->) R ; Ka (96->) R+H ; Windstar (95->) H
- **GAZ** 2410, 3102, 31029 L ; 3110, 3307, 4301 ( ) L
- **HYUNDAI** Atos (97->) R ; H100/H350/H600 (94->00) H ; Pony (89->94) H ; Pony (94->) H ; Terracan (02->) H
- **ISUZU** Trooper (88->92) L
- **JAGUAR** XJ s. III (79->93) L
- **KIA** Joice (99->) H ; Sportage (93->) H
- **LANCIA** Y 10 (84->93) L ; Ypsilon (96->) R
- **MAZDA** 121 (91->95) R ; 626 (87->91) H ; 626 (91->97) H ; Demio (98->) R +H ; MPV (94->99) H ;
- **MPV** (00->) H ; Premacy (99->) R
- **MERCEDES** Bus 207-410 (T1) (88->) ; G (W463) (93->) L
- **MINI** Cooper (99->) R ; Roadster (99->) R ; Cabriolet (99->) R ; Pajero Pinin (99->) H ; Pajero Sport/Montero (98->) H ; Santamo (99->) H ; Space Runner (91->) H
- **NISSAN** Almera (00->) R ; Micra (03->) R ; Prairie Pro (92->) H ; Serena (93->) H
- **OPEL** Astra (91->) H ; Astra II (98->) H ; Corsa A (82->93) L +H ; Corsa B (93->00) H ; Omega B (94->) com.H ; Vectra B (95->02) com.H
- **PEUGEOT** 106 (91->) H ; 206 (98->) R ; Expert (96->) H
- **RENAULT** Clio I (90->94) H ; Clio I (94->98) H ; Express / Rapid (85->96) H
- **ROVER** 100 (90->) L
- **SAAB** 90 (84->87) L ; 900 (87->93) L
- **SEAT** Inca (95->) H ; Marbella (86->96) L
- **SUBARU** Domingo (93->) L +H ; Justy (89->) H ; Legacy (89->) H ; Libero (92->) L
- **SUZUKI** Alto (86->94) L ; Alto (94->) R ; Carry (99->) L ; Swift (92->) H
- **ŠKODA** 105 / 120 (81->90) L ; Favorit (88->93) H ; Favorit (93->95) H ; Felicia (94->) H ; Forman (90->) H
- **TOYOTA** Corolla (87-> 01) com.H ; Corolla (sedan, combi) (02->) R ; Hiace (90->95) H ; Land Cruiser J6 (87->91) L ; Lexus LS400 (90->) R ; Lite Ace (88->92) H ; Lite Ace (92->) H ; Picnic (96->) R ; Starlet (90->00) H ; Yaris Verso (99->) R
- **VOLVO** 240, 260 (74->93) L ; 850 (91->98) H ; C 70, S 70, V 70 (97->) H ; S 40, V 40 (96->) H
- **VW** Golf II (83->92) H ; Passat (88->97) H ; Polo (81->94) L +H ; Taro (90->) L ; Transporter (81->90) H
- **WARTBURG** 1, 3, 353 W L
- **ZASTAVA** Yugo 45 (81->) L ; Yugo Florida (89->) L

# 18" -PCS-MS

450 MM

- **ALFA ROMEO** L ; Alfa 33 (90->95) L +H ; Alfa 75 (85->92) L
- **AUDI** 80 / 90 (78->84) L ; 100 (90->94) com.H ; A 6 (94->) com.H
- **BMW** Series 3 (75->84) L ; Series 3 (82->91) H ; Series 3 (92->96) H ; Series 5 (81->90) L ; Series 7 (77->87) L
- **CHRYSLER** Neon (96->98) R
- **CITROËN** Saxo (96->) R ; Xsara (97->) H ; ZX (91->) H ; XM (89->94) H
- **DAEWOO** Korando (96->) L ; Musso (93->96) L ; Musso (96->) R ; Nexia (94->) L+H ; Tico (91->) L
- **DAIHATSU** Applause (89->) L ; Charade (83->87) L ; Charade (87->90) L ; Charade (90->) R. ; Cuore (97->01) L ; Cuore (01->) L ; Sirion (98->) R
- **FIAT** Doblo (00->) R ; Punto II (00->) R ; Siena ; Palio W. (97->) R
- **FORD** Escort (80->90) L+H ; Orion (83->90) L
- **HONDA** CRX (87->92) L+H ; CRX (92->01) R +H ; Civic (83->87) L ; Civic (87->91) H ; Civic (91->01) R +H ; Civic Aerodeck (98->) R ; Concerto (89->95) L +H ; Integra (98->) R +H ; Insight (00->) R
- **HYUNDAI** Accent (94->) R ; Coupe (96->) R ; H100/H350/H600 (94->00) L ; Lantra / Elantra (90->95) R. ; Lantra / Elantra (95->) R ; Pony (89->94) L ; Pony (94->) L ; Santamo (99->) R ; S-Coupe (89->) R ; Sonata I (88->93) R
- **ISUZU** Campo (89->) L ; Gemini (84->) L
- **JEEP** Cherokee (88->) L
- **KIA** Carens (00->) R ; Carnival (98->) H ; Joice (99->) R ; Leo (96->) H ; Pregio (98->) H ; Pride (90->01) L ; Sephia / Sephia II (93->) H
- **LADA** Samara 2108 - 09 T ; Samara 2110 - 2112 ( ) H
- **LANCIA** Delta (85->93) L +H
- **MAZDA** 121 (87->91) L ; 323 (94->98) R ; 323 (97->) R ; 323C / F / R / S (89->94) R ;
- **MX3** (91->) R ; RX7 (87->96) H
- **MINI** Cooper (99->) R ; Roadster (99->) R ; Cabriolet (99->) R ; Pajero Pinin (99->) H ; Pajero Sport/Montero (98->) H ; Santamo (99->) H ; Space Runner (91->) H ; Space Star (98->) R ; Space Wagon (91->) R
- **NISSAN** 200 SX (88->94) H ; Almera Tino (00->) R ; Micra (82->92) L +H ; Micra (92->03) R +H ; Patrol GR (94->97) L ; Sunny (->90) H ; Vanette (85->90) L
- **OPEL** Agila (00->) R ; Ascona (81->88) L ; Astra (91->) L ; Campo (91->) L ; Combo (94->) L ; Corsa B (93->00) L ; Kadett (84->91) L ; Tigra (94->) L
- **PEUGEOT** 106 (91->) R ; 205 (83->96) L +H ; 305 (82->90) L +com.H ; 309 (85->93) L +H ; 505 (79->92) L +com.H
- **RENAULT** Clio I (90->94) L ; Clio II / Clio III (98->) R ; Express / Rapid (85->96) L ; Laguna I (94->01) R ; R 21 (86->) H ; R 5 (84->96) L ; Trafic (80->89) L
- **ROVER** 200 (85->95) L +H ; 200 (95->00) L +H ; 25 (00->) L +H ; 400 (90->95) L ; 400 (95->00) R +H ; 45 (00->) R ; Discovery I (89->98) L ; Range Rover (-> 94) L +H
- **SAAB** 900 Cabriolet (89->93) L
- **SEAT** Inca (95->) R ; Malaga (89->93) L
- **SUBARU** Impreza (92->) R ; Justy (89->) L

<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>18"-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>450 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>SUZUKI</b> Baleno (94-&gt;) R ; Swift (84-&gt;89) L ; Swift (89-&gt;91) R ; Swift (92-&gt;) R ; Vitara (89-&gt;) L ; Wagon R+ (97-&gt;) R</li> <li>• <b>ŠKODA</b> Fabia (00-&gt;) R ; Favorit (88-&gt;93) L</li> <li>• <b>TOYOTA</b> 4 Runner (89-&gt;96) L ; Avensis (97-&gt;) R ; Camry (86-&gt;91) R ; Carina E (92-&gt;) R ; Carina II (87-&gt;92) R ; Celica (87-&gt;93) R ; Corolla (87-&gt; 01) R ; Corolla (hatchback) (02-&gt;) R ; Hiace (95-&gt;) H ; J7 (85-&gt;) L ; J8 (90-&gt;) L ; Lite Ace (92-&gt;) L ; Paseo (95-&gt;) R ; RAV 4 (94-&gt;00) R ; Starlet (90-&gt;00) R ; Supra (89-&gt;95) R</li> <li>• <b>VOLVO</b> 240, 260 (74-&gt;93) H ; 340, 360 (79-&gt;91) L +H</li> <li>• <b>VW</b> Bora (98-&gt;) R ; Caddy (95-&gt;) R ; Corrado (88-&gt;96) H ; Golf IV (97-&gt;) R ; Passat (82-&gt;88) L ; Polo Classic (95-&gt;99) R ; Polo Classic (99-&gt;02) R ; Transporter (81-&gt;90) L ; Transporter T4 (90-&gt;) H</li> </ul>
<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>19"-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>480 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> R ; Alfa 155 (92-&gt;96) R ; Alfa 166 (98-&gt;) R</li> <li>• <b>AUDI</b> A 3 (96-&gt;) R</li> <li>• <b>CHRYSLER</b> Neon (99-&gt;) R</li> <li>• <b>CITROËN</b> C 15 (84-&gt;)</li> <li>• <b>DAEWOO</b> Espero (94-&gt;) L ; Lanos (97-&gt;) L +H ; Leganza (97-&gt;) R ; Tacuma (00-&gt;) R</li> <li>• <b>DAIHATSU</b> Charade (90-&gt;) L ; Grand Move (96-&gt;) R ; Move (99-&gt;) L ; Sirion (98-&gt;) L</li> <li>• <b>FIAT</b> Brava (95-&gt;) R +H ; Bravo (95-&gt;) R ; Cinquecento (91-&gt;98) L ; Marea (96-&gt;) R ; Seicento (98-&gt;) L ; Stilo (01-&gt;) R ; Tipo (83-&gt;93) L ; Uno (83-&gt;)</li> <li>• <b>FORD</b> Fiesta (89-&gt;) L ; Focus (98-&gt;) R ; Ka (96-&gt;) L ; Maverick (00-&gt;) L ; Puma (97-&gt;) L +H</li> <li>• <b>HONDA</b> Accord (89-&gt;) R ; CR-V (97-&gt;) L ; CRX (01-&gt;) R ; Civic (87-&gt;91) L ; Jazz (02-&gt;) R ; Legend (91-&gt;) R ; Prelude (91-&gt;) R</li> <li>• <b>HYUNDAI</b> S-Coupe (89-&gt;) L</li> <li>• <b>KIA</b> Clarus (96-&gt;) R ; K2700 ( ) R ; Leo (96-&gt;) R ; Pregio (98-&gt;) R ; Rio (00-&gt;) R ; Sephia / Sephia II (93-&gt;) R ; Shuma / Shuma II (97-&gt;) R</li> <li>• <b>LANCIA</b> Delta (93-&gt;00) R</li> <li>• <b>MAZDA</b> 121 (96-&gt;) L ; 626 (87-&gt;91) L ; 626 (91-&gt;97) R ; 626 (97-&gt;01) R ; Xedos 6 (92-&gt;) R ; Xedos 9 (93-&gt;) R</li> <li>• <b>MITSUBISHI</b> Colt / Mirage (95-&gt;) R ; Galant (92-&gt;97) R ; Lancer (95-&gt;) R ; Pajero / Montero (90-&gt;00) L ; Pajero Pinin (99-&gt;) L ; Sigma (90-&gt;) R</li> <li>• <b>NISSAN</b> Almera (95-&gt;00) R ; Navara (98-&gt;) L ; Patrol (85-&gt;94) L ; Patrol GR (98-&gt;) L ; Primera (90-&gt;) R ; Sunny (-&gt;90) L ; Sunny (90-&gt;) R ; Terrano (86-&gt;93) L ; Urvan (93-&gt;) L ; Vanette (90-&gt;96) R.</li> <li>• <b>OPEL</b> Ascona (81-&gt;88) H ; Astra II (98-&gt;) R ; Calibra (90-&gt;) L +H ; Frontera (91-&gt;) L ; Omega A (86-&gt;94) L ; Omega B (94-&gt;) R ; Vectra A (88-&gt;95) L +H ; Vectra B (95-&gt;02) L</li> <li>• <b>RENAULT</b> R 19 (88-&gt;) H</li> <li>• <b>SEAT</b> Arosa (97-&gt;99) L ; Arosa (99-&gt;) R ; Cordoba (93-&gt;) R ; Ibiza (89-&gt;93) +H ; Ibiza (93-&gt;01) R ; Leon (99-&gt;) R ; Toledo (98-&gt;) R</li> <li>• <b>SUBARU</b> Forester (97-&gt;) R ; Legacy (89-&gt;) R ; Vivio (92-&gt;) L</li> <li>• <b>SUZUKI</b> Alto (94-&gt;) L ; Grand Vitara (98-&gt;) L</li> <li>• <b>ŠKODA</b> Octavia (96-&gt;) R</li> <li>• <b>TOYOTA</b> Camry (91-&gt;00) R ; Camry (01-&gt;) R ; Celica (93-&gt;99) R ; Hiace (90-&gt;95) L ; Lexus GS300 (93-&gt;98) R ; Lexus IS200 (98-&gt;) R ; RAV 4 (00-&gt;) R</li> <li>• <b>VOLVO</b> 440, 460, 480 (86-&gt;96)</li> <li>• <b>VW</b> Corrado (88-&gt;96) L ; Golf III (91-&gt;97) R ; LT (82-&gt;96) L ; Lupo (98-&gt;) L ; Polo (94-&gt;99) L ; Polo (99-&gt;01) L ; Vento (91-&gt;) R.</li> </ul>
<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>20"-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>510 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>AUDI</b> R ; TT (98-&gt;) R</li> <li>• <b>AZLK</b> Moskvitch - Aleko 2141 L</li> <li>• <b>BMW</b> Series 3 (82-&gt;91) L ; Series 3 (92-&gt;96) R ; Series 3 (97-&gt;) R ; Z3 (96-&gt;) L</li> <li>• <b>CHRYSLER</b> PT Cruiser (00-&gt;) L</li> <li>• <b>CITROËN</b> BX (82-&gt;) +H ; Saxo (96-&gt;) L ; Xantia (93-&gt;) R ; Xsara (97-&gt;) R ; XM (94-&gt;) R</li> <li>• <b>DAEWOO</b> Lublin II L ; Musso (96-&gt;) L ; Nubira (97-&gt;) L ; Polonez (94-&gt;) L +H</li> <li>• <b>DAIHATSU</b> Grand Move (96-&gt;) L ; Terios (97-&gt;) L</li> <li>• <b>FIAT</b> Croma (85-&gt;96) L ; Ducato (81-&gt;94) L ; Marea (96-&gt;) H</li> <li>• <b>FORD</b> Escort (90-&gt;98) L ; Maverick (93-&gt;99) R ; Mondeo (93-&gt;01) R +com.H ; Mondeo (01-&gt;) R ; Orion (90-&gt;93) L ; Probe (93-&gt;) L +H ; Scorpio (85-&gt;98) L +H ; Scorpio (93-&gt;) L ; Sierra (82-&gt;93) L +H ; Sierra combi ( ) L ; Windstar (95-&gt;) R</li> <li>• <b>GAZ</b> Gazel 3302 L</li> <li>• <b>HONDA</b> CRX (92-&gt;01) L ; Civic (91-&gt;01) L ; Civic Aerodeck (98-&gt;) L ; HRV (98-&gt;) L ; Integra (98-&gt;) L ; Insight (00-&gt;) L ; Jazz (02-&gt;) L ; Logo (99-&gt;01) L</li> <li>• <b>HYUNDAI</b> Accent (94-&gt;) L +H ; Atos (97-&gt;) L ; H1 / H200 (99-&gt;) R ; Lantra / Elantra (95-&gt;) L ; Santa Fe (01-&gt;) R ; Sonata II (93-&gt;96) L ; Sonata III (96-&gt;98) L ; Sonata III (98-&gt;) R ; Terracan (02-&gt;) R ; XG (98-&gt;) R</li> <li>• <b>ISUZU</b> Trooper (92-&gt;) L</li> <li>• <b>JAGUAR</b> Sovereign (92-&gt;) L ; XJ s. IV (94-&gt;) L</li> <li>• <b>KIA</b> Magentis (01-&gt;) R ; Sportage (93-&gt;) L</li> <li>• <b>LADA</b> Samara 2108 - 09 L ; Samara 2110 - 2112 ( ) L ; Oka 1111, 1113 ( )</li> <li>• <b>LANCIA</b> Delta (93-&gt;00) H ; Kappa (94-&gt;01) R ; Thema (84-&gt;94) L</li> <li>• <b>MAZ</b> Super L</li> <li>• <b>MAZDA</b> 121 (91-&gt;95) L ; 323 (94-&gt;98) H ; Demio (98-&gt;) L ; MPV (94-&gt;99) R ; MX6 (91-&gt;) L ; RX7 (87-&gt;96) L</li> <li>• <b>MERCEDES</b> 200D-280E (W123) (76-&gt;85) L ; Bus 207-410 (T1) (88-&gt;) L ; MB 100D (87-&gt;) L</li> <li>• <b>MITSUBISHI</b> 3000 GT (91-&gt;01) R ; Carisma (95-&gt;) R +H ; Colt / Mirage (88-&gt;95) L ; Eclipse (91-&gt; 95) L ; Eclipse (96-&gt;) H ; Lancer (92-&gt;95) L ; Pajero / Montero (00-&gt;) L ; Pajero Sport/Montero (98-&gt;) L</li> <li>• <b>NISSAN</b> 200 SX (88-&gt;94) L ; 200 SX (94-&gt;) R ; Almera Tino (00-&gt;) H ; Bluebird (86-&gt;94) L ; Maxima (88-&gt;95) L ; Micra (92-&gt;03) L ; Primera (90-&gt;) com.H ; Primera (99-&gt;01) R ; Sunny (90-&gt;) hatch.T ; Terrano II (93-&gt;96) R ; Terrano II (02-&gt;) R</li> </ul>

## 20"-PCS-MS

510 MM

- **OPEL** Agila (00->) L ; Arena () L ; Astra II (98->) L ; Combo (01->) L ; Corsa C (01->) L ; Monterey (92->) L ; Tigra (94->) H
- **PEUGEOT** 106 (91->) L ; 306 (93->) R +H ; Expert (96->) R ; Express (82->94) L ; J5 (81->94) L
- **RENAULT** Clio I (94->98) L ; Megane (96->02) R +com.H ; R 19 (88->) L ; R 21 (86->) L ; Trafic (89->00) L
- **ROVER** 400 (95->00) L ; 45 (00->) L ; 600 (93->99) R ; 800 (91->99) L ; Maestro (83->94) L +H
- **SAAB** 9-3 (98->) H ; 900 (87->93) H ; 900 (93->98) H ; 9000 (84->98) H
- **SEAT** Toledo (91->98) L
- **SUBARU** Legacy (99->) R ; SVX (91->97) R
- **SUZUKI** Baleno (94->) L ; Swift (89->91) L ; Wagon R+ (97->) L
- **ŠKODA** Favorit (93->95) L ; Felicia (94->) L ; Felicia pick-up (95->) L ; Forman (90->) L
- **TOYOTA** Avensis (97->) com.H ; Camry (86->91) L ; Carina E (92->) com.H ; Carina II (87->92) L ; Celica (87->93) L ; Celica (93->99) H ; Corolla (87-> 01) L ; Lexus GS300 (98->) R ; Paseo (95->) L ; RAV 4 (94->00) L ; Starlet (90->00) L ; Supra (89->95) L ; Supra (95->) R
- **VOLVO** 440, 460, 480 (86->96) H ; 740, 760, 780 (83->95) L ; 940 (90->97) L ; S 40, V 40 (96->) R
- **VW** Caddy (82->92) L ; Passat B5 (96->) R.

## 21"-PCS-MS

530 MM

- **ALFA ROMEO** L ; Alfa 155 (92->96) L ; Alfa 156 (97->) P ; Alfa 164 (87->98) L ; Alfa 166 (98->) L
- **AUDI** 80 / 90 (84->94) L ; 100 (82->90) L +H ; 200 (83->91) L +H ; Allroad Quattro (00->) R ; A 3 (96->) L ; A 4 (94->99) L ; A 4 (99->) R ; A 6 (94->) R ; A 8 (94->) R ; TT (98->) L
- **BMW** Series 3 (92->96) L
- **CHRYSLER** Neon (96->98) L ; PT Cruiser (00->) R
- **DAEWOO** Matiz (98->) L
- **DAIHATSU** YRV (01->) L
- **FORD** Maverick (93->99) L ; Mondeo (93->01) L
- **HONDA** CRX (01->) L ; Legend (91->) L ; Prelude (91->) L
- **HYUNDAI** Lantra / Elantra (90->95) L ; Sonata I (88->93) L
- **JAGUAR** Sovereign (86->93) ; XJ6 (86->) ; XK8 (96->) L
- **KIA** Clarus (96->) L ; K2700 () L ; Leo (96->) L ; Pregio (98->) L ; Rio (00->) L ; Sephia / Sephia II (93->) L ; Shuma / Shuma II (97->) L
- **LANCIA** Delta (93->00) L ; Lybra (99->) R
- **MAZDA** 323 (94->98) L ; 323 (97->) L ; 323C / F / P / S (89->94) L ; 626 (91->97) L ; 626 (97->01) L +H ; MX3 (91->) L +H ; Xedos 6 (92->) L ; Xedos 9 (93->) L
- **MERCEDES** Sprinter (95->) R
- **MITSUBISHI** 3000 GT (91->01) L ; Carisma (95->) L ; Colt / Mirage (95->) L ; Eclipse (96->) R ; Galant (92->97) L ; Lancer (95->) L ; Sigma (90->) L ; Space Star (98->) L
- **NISSAN** 200 SX (94->) L ; Almera (95->00) L ; Maxima QX (94-> 00) R ; Micra (03->) L ; Pathfinder (98->) R ; Primera (90->) L ; Primera (99->01) L +com.H ; Sunny (90->) L ; Terrano II (93->96) L ; Terrano II (97->01) R ; Terrano II (02->) L
- **OPEL** Vivaro (01->) R
- **RENAULT** Clio II / Clio III (98->) L ; Kangoo (97->) L ; Trafic (01->) R
- **ROVER** Freelander (97->) L
- **SAAB** 9-3 (98->) L ; 900 (93->98) L ; 9000 (84->98) L
- **SEAT** Arosa (99->) L ; Cordoba (93->) L ; Ibiza (93->01) L ; Inca (95->) L ; Leon (99->) L ; Toledo (98->) L
- **SUBARU** Forester (97->) L ; Impreza (92->) L ; Legacy (89->) L
- **SUZUKI** Swift (92->) L
- **ŠKODA** Fabia (00->) L ; Octavia (96->) L
- **TOYOTA** Avensis (97->) L ; Camry (91->00) L ; Carina E (92->) L ; Celica (93->99) L ; Hiace (95->) L ; Lexus GS300 (93->98) L ; Supra (95->) L ; Yaris (99->) L
- **VOLVO** 440, 460, 480 (86->96) L ; 850 (91->98) L ; 960 (90->97) L ; C 70, S 70, V 70 (97->) L ; S 40, V 40 (96->) L ; S 90, V 90 (96->98) L
- **VW** Bora (98->) L ; Caddy (95->) L ; Golf III (91->97) L ; Golf IV (97->) L ; LT (96->) R ; Passat (88->97) L ; Passat B5 (96->) L ; Polo Classic (95->99) L ; Polo Classic (99->02) L ; Transporter T4 (90->) L ; Vento (91->) L
- **ZAZ** Tavria (88->) L

15" SPO-PCS-MS	380 MM	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> H; Audi A3 (96-&gt;) H, A4 (94-&gt;99) H;</li> <li>• <b>DAEWOO</b> Nubira (97-&gt;) H, Tacuma (00-&gt;) H;</li> <li>• <b>FORD</b> Focus (98-&gt;) H;</li> <li>• <b>HONDA</b> Accord (89-&gt;) H, Civic (83-&gt;87) H, Civic Aerodeck (98-&gt;) H, Shuttle (94-&gt;) H; Isuzu Trooper (92-&gt;) H;</li> <li>• <b>KIA</b> Clarus (96-&gt;) H, Pride (90-&gt;01) H, Rio (00-&gt;) H;</li> <li>• <b>LADA</b> 2101-07 L, Niva (94-&gt;) L,</li> <li>• <b>MAZDA</b> 121 (87-&gt;95) H;</li> <li>• <b>MERCEDES</b> W124 (84-&gt;96) H, W123 (76-&gt;85) H, W210 (95-&gt;) H, Klasa G (93-&gt;) H, ML (97-&gt;) H;</li> <li>• <b>MITSUBISHI</b> Pajero/Montero (90-&gt;00) H;</li> <li>• <b>NISSAN</b> Bluebird (86-&gt;94) H, Patrol GR (98-&gt;) H, Primera (99-&gt;01) H, Vanette (85-&gt;96) H, X-Trail (01-&gt;) R;</li> <li>• <b>OPEL</b> Monterey (92-&gt;) H,</li> <li>• <b>PEUGEOT</b> Express (82-&gt;94) H;</li> <li>• <b>RENAULT</b> R5 (84-&gt;96) H;</li> <li>• <b>SUBARU</b> Forester (97-&gt;) H, Impreza (92-&gt;) H;</li> <li>• <b>SUZUKI</b> Baleno (94-&gt;) H, Carry (89-&gt;98) L, Grand Vitara (98-&gt;) H, Swift (84-&gt;89) H, Vitara (89-&gt;) H;</li> <li>• <b>VW</b> Passat (82-&gt;88) H, Passat B5 (96-&gt;) H</li> </ul>
16" SPO-PCS-MS	410 MM	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> L, 147 (01-&gt;)R;</li> <li>• <b>AUDI</b> 80/90 (84-&gt;94)H;</li> <li>• <b>CITROEN</b> AX (86-&gt;)H, CX (82-&gt;93)H, Saxo (96-&gt;)H, XM (94-&gt;)H;</li> <li>• <b>DAEWOO</b> Matiz (98-&gt;)R, Tico (91-&gt;)R,</li> <li>• <b>FIAT</b> Panda (80-&gt;03)L, Punto (93-&gt;00)R;</li> <li>• <b>FORD</b> Fiesta (83-&gt;89)L+H, Fiesta (89-&gt;)H, Fiesta (02-&gt;)R, Ka (96-&gt;)R+H, Windstar (95-&gt;)H,</li> <li>• <b>GAZ</b> 2410, 3102, 31029, 3110, 3307,4301 L;</li> <li>• <b>HYUNDAI</b> Atos (97-&gt;)R, H100/H350/H600 (94-&gt;00)H, Pony (86-&gt;)H, Terracan (02-&gt;)H;</li> <li>• <b>ISUZU</b> Trooper (88-&gt;92)L;</li> <li>• <b>JAGUAR</b> XJS III (79-&gt;93)L;</li> <li>• <b>KIA</b> Joyce (99-&gt;)H, Sportage (93-&gt;)H;</li> <li>• <b>MAZDA</b> 121 (91-&gt;95)R, 626 (91-&gt;97)H, MPV (94-&gt;99)H, MPV (00-&gt;)H, Premacy (99-&gt;)R;</li> <li>• <b>MERCEDES</b> Bus 207-410 (88-&gt;), G Klasa (93-&gt;)L;</li> <li>• <b>MITSUBISHI</b> Galant (92-&gt;97)H, Lancer (95-&gt;)H, Pajero Pinin (99-&gt;)H, Pajero Sport/Montero (98-&gt;)H, Space Runner (91-&gt;)H;</li> <li>• <b>NISSAN</b> Almera (00-&gt;)R, Micra (03-&gt;)R, Praire Pro (92-&gt;)H, Serena (93-&gt;)H;</li> <li>• <b>OPEL</b> Astra (91-&gt;)H, Astra II (98-&gt;)H, Corsa A (82-&gt;93)L+H, Corsa B (93-&gt;00)H, Omega B (94-&gt;)H, Vectra B(95-&gt;02)H;</li> <li>• <b>PEUGEOT</b> 106 (91-&gt;)H, 206(98-&gt;)R, Expert (96-&gt;)H;</li> <li>• <b>RENAULT</b> Clio I (90-&gt;98)H, Express/Rapid (85-&gt;96)H;</li> <li>• <b>SEAT</b> Inca (95-&gt;)H;</li> <li>• <b>SUBARU</b> Justy (89-&gt;)H, Legacy (89-&gt;)H, Libero (92-&gt;)L;</li> <li>• <b>SUZUKI</b> Alto (86-&gt;94)L, Alto (94-&gt;)R, Carry (99-&gt;)L, Swift (92-&gt;)H;</li> <li>• <b>SKODA</b> 105/120 (81-&gt;90)L, Favorit (88-&gt;95)H, Felicia (94-&gt;)H;</li> <li>• <b>TOYOTA</b> Corolla (87-&gt;01)H, Corolla (02-&gt;)R, Hiace (90-&gt;95)H, Land Cruiser (87-&gt;91)L, Picnic (96-&gt;)R,</li> <li>• <b>STARLET</b> (90-&gt;00)H, Yaris Verso (99-&gt;)R;</li> <li>• <b>VOLVO</b> 240,260 (74-&gt;93)L, 850 (91-&gt;98)H, C70/S70/V70 (97-&gt;)H, S40/V40 (96-&gt;)H;</li> <li>• <b>VW</b> Golf II(83-&gt;92)H, Passat (88-&gt;97)H, Polo(81-&gt;94)L+H, Transporter(81-&gt;90)H</li> <li>• <b>WARTBURG</b> 1.3, 353 L</li> </ul>
18" SPO-PCS-MS	450 MM	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> L ; Alfa 33 (90-&gt;95) L +H ; Alfa 75 (85-&gt;92) L</li> <li>• <b>AUDI</b> 80 / 90 (78-&gt;84) L ; 100 (90-&gt;94) com.H ; A 6 (94-&gt;) com.H</li> <li>• <b>BMW</b> Series 3 (75-&gt;84) L ; Series 3 (82-&gt;91) H ; Series 3 (92-&gt;96) H ; Series 5 (81-&gt;90) L ; Series 7 (77-&gt;87) L</li> <li>• <b>CHRYSLER</b> Neon (96-&gt;98) R</li> <li>• <b>CITROËN</b> Saxo (96-&gt;) R ; Xsara (97-&gt;) H ; ZX (91-&gt;) H ; XM (89-&gt;94) H</li> <li>• <b>DAEWOO</b> Korando (96-&gt;) L ; Musso (93-&gt;96) L ; Musso (96-&gt;) R ; Nexia (94-&gt;) L +H ; Tico (91-&gt;) L</li> <li>• <b>DAIHATSU</b> Applause (89-&gt;) L ; Charade (83-&gt;87) L ; Charade (87-&gt;90) L ; Charade (90-&gt;) R. ; Cuore (97-&gt;01) L ; Cuore (01-&gt;) L ; Sirion (98-&gt;) R</li> <li>• <b>FIAT</b> Doblo (00-&gt;) R ; Punto II (00-&gt;) R ; Siena; Palio W. (97-&gt;) R</li> <li>• <b>FORD</b> Escort (80-&gt;90) L +H ; Orion (83-&gt;90) L</li> <li>• <b>HONDA</b> CRX (87-&gt;92) L +H ; CRX (92-&gt;01) R +H ; Civic (83-&gt;87) L ; Civic (87-&gt;91) H ; Civic (91-&gt;01) R +H ; Civic Aerodeck (98-&gt;) R ; Concerto (89-&gt;95) L +H ; Integra (98-&gt;) R +H ; Insight (00-&gt;) R</li> <li>• <b>HYUNDAI</b> Accent (94-&gt;) R ; CouRe (96-&gt;) R ; H100/H350/H600 (94-&gt;00) L ; Lantra / Elantra (90-&gt;95) R. ; Lantra / Elantra (95-&gt;) R ; Pony (89-&gt;94) L ; Pony (94-&gt;) L ; Santamo (99-&gt;) R ; S-Coupe (89-&gt;) R. ; Sonata I (88-&gt;93) R</li> <li>• <b>ISUZU</b> Campo (89-&gt;) L ; Gemini (84-&gt;) L</li> <li>• <b>JEEP</b> Cherokee (88-&gt;) L</li> <li>• <b>KIA</b> Carens (00-&gt;) R ; Carnival (98-&gt;) H ; Joice (99-&gt;) R ; Leo (96-&gt;) H ; Pregio (98-&gt;) H ; Pride (90-&gt;01) L ; Sephia / Sephia II (93-&gt;) H</li> <li>• <b>LADA</b> Samara 2108 - 09 T ; Samara 2110 - 2112 () H</li> <li>• <b>LANCIA</b> Delta (85-&gt;93) L +H</li> <li>• <b>MAZDA</b> 121 (87-&gt;91) L ; 323 (94-&gt;98) R ; 323 (97-&gt;) R ; 323C / F / P / S (89-&gt;94) R ; MX3 (91-&gt;) R. ; RX7 (87-&gt;96) H</li> <li>• <b>MITSUBISHI</b> Canter (88-&gt;) L ; Colt / Mirage (88-&gt;95) R ; Eclipse (91-&gt; 95) H ; Galant (97-&gt;) R. ; L200 (86-&gt;) L ; Lancer (92-&gt;95) R +H ; Santamo (99-&gt;) R ; Space Runner (91-&gt;) R. ; Space Star (98-&gt;) R. ; Space Wagon (91-&gt;) R</li> <li>• <b>NISSAN</b> 200 SX (88-&gt;94) H ; Almera Tino (00-&gt;) R ; Micra (82-&gt;92) L +H ; Micra (92-&gt;03) R +H ; Patrol GR (94-&gt;97) L ; Sunny (-&gt;90) H ; Vanette (85-&gt;90) L</li> </ul>

18" SPO-PCS-MS	450 MM	<ul style="list-style-type: none"> <li>• <b>OPEL</b> Agila (00-&gt;) R ; Ascona (81-&gt;88) L ; Astra (91-&gt;) L ; Campo (91-&gt;) L ; Combo (94-&gt;) L ; Corsa B (93-&gt;00) L ; Kadett (84-&gt;91) L ; Tigra (94-&gt;) L</li> <li>• <b>PEUGEOT</b> 106 (91-&gt;) R ; 205 (83-&gt;96) L +H ; 305 (82-&gt;90) L +com.H ; 309 (85-&gt;93) L +H ; 505 (79-&gt;92) L +com.H</li> <li>• <b>RENAULT</b> Clio I (90-&gt;94) L ; Clio II / Clio III (98-&gt;) R ; Express / Rapid (85-&gt;96) L ; Laguna I (94-&gt;01) R ; R 21 (86-&gt;) H ; R 5 (84-&gt;96) L ; Trafic (80-&gt;89) L</li> <li>• <b>ROVER</b> 200 (85-&gt;95) L +H ; 200 (95-&gt;00) L +H ; 25 (00-&gt;) L +H ; 400 (90-&gt;95) L ; 400 (95-&gt;00) R +H ; 45 (00-&gt;) R ; Discovery I (89-&gt;98) L ; Range Rover (-&gt; 94) L +H</li> <li>• <b>SAAB</b> 900 Cabriolet (89-&gt;93) L</li> <li>• <b>SEAT</b> Inca (95-&gt;) R ; Malaga (89-&gt;93) L</li> <li>• <b>SUBARU</b> Impreza (92-&gt;) R ; Justy (89-&gt;) L</li> <li>• <b>SUZUKI</b> Baleno (94-&gt;) R ; Swift (84-&gt;89) L ; Swift (89-&gt;91) R ; Swift (92-&gt;) R ; Vitara (89-&gt;) L ; Wagon R+ (97-&gt;) R</li> <li>• <b>ŠKODA</b> Fabia (00-&gt;) R ; Favorit (88-&gt;93) L</li> <li>• <b>TOYOTA</b> 4 Runner (89-&gt;96) L ; Avensis (97-&gt;) R ; Camry (86-&gt;91) R ; Carina E (92-&gt;) R ; Carina II (87-&gt;92) R ; Celica (87-&gt;93) R ; Corolla (87-&gt; 01) R ; Corolla (hatchback) (02-&gt;) R ; Hiace (95-&gt;) H ; J7 (85-&gt;) L ; J8 (90-&gt;) L ; Lite Ace (92-&gt;) L ; Paseo (95-&gt;) R ; RAV 4 (94-&gt;00) R ; Starlet (90-&gt;00) R ; Supra (89-&gt;95) R</li> <li>• <b>VOLVO</b> 240, 260 (74-&gt;93) H ; 340, 360 (79-&gt;91) L +H</li> <li>• <b>VW</b> Bora (98-&gt;) R ; Caddy (95-&gt;) R ; Corrado (88-&gt;96) H ; Golf IV (97-&gt;) R ; Passat (82-&gt;88) L ; Polo Classic (95-&gt;99) R ; Polo Classic (99-&gt;02) R ; Transporter (81-&gt;90) L ; Transporter T4 (90-&gt;) H</li> </ul>
19" SPO-PCS-MS	480 MM	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> R ; Alfa 155 (92-&gt;96) R ; Alfa 166 (98-&gt;) R</li> <li>• <b>AUDI</b> A 3 (96-&gt;) R</li> <li>• <b>CHRYSLER</b> Neon (99-&gt;) R</li> <li>• <b>CITROËN</b> C 15 (84-&gt;)</li> <li>• <b>DAEWOO</b> Espero (94-&gt;) L ; Lanos (97-&gt;) L +H ; Leganza (97-&gt;) R ; Tacuma (00-&gt;) R</li> <li>• <b>DAIHATSU</b> Charade (90-&gt;) L ; Grand Move (96-&gt;) R ; Move (99-&gt;) L ; Sirion (98-&gt;) L</li> <li>• <b>FIAT</b> Brava (95-&gt;) R +H ; Bravo (95-&gt;) R ; Cinquecento (91-&gt;98) L ; Marea (96-&gt;) R ; Seicento (98-&gt;) L ; Stilo (01-&gt;) R ; Tipo (83-&gt;93) L ; Uno (83-&gt;)</li> <li>• <b>FORD</b> Fiesta (89-&gt;) L ; Focus (98-&gt;) R ; Ka (96-&gt;) L ; Maverick (00-&gt;) L ; Puma (97-&gt;) L +H</li> <li>• <b>HONDA</b> Accord (89-&gt;) R ; CR-V (97-&gt;) L ; CRX (01-&gt;) R ; Civic (87-&gt;91) L ; Jazz (02-&gt;) R ; Legend (91-&gt;) R ; Prelude (91-&gt;) R</li> <li>• <b>HYUNDAI</b> S-Coupe (89-&gt;) L</li> <li>• <b>KIA</b> Clarus (96-&gt;) R ; K2700 () R ; Leo (96-&gt;) R ; Pregio (98-&gt;) R ; Rio (00-&gt;) R ; Sephia / Sephia II (93-&gt;) R ; Shuma / Shuma II (97-&gt;) R</li> <li>• <b>LANCIA</b> Delta (93-&gt;00) R</li> <li>• <b>MAZDA</b> 121 (96-&gt;) L ; 626 (87-&gt;91) L ; 626 (91-&gt;97) R ; 626 (97-&gt;01) R ; Xedos 6 (92-&gt;) R ; Xedos 9 (93-&gt;) R</li> <li>• <b>MITSUBISHI</b> Colt / Mirage (95-&gt;) R ; Galant (92-&gt;97) R ; Lancer (95-&gt;) R ; Pajero / Montero (90-&gt;00) L ; Pajero Pinin (99-&gt;) L ; Sigma (90-&gt;) R</li> <li>• <b>NISSAN</b> Almera (95-&gt;00) R ; Navara (98-&gt;) L ; Patrol (85-&gt;94) L ; Patrol GR (98-&gt;) L ; Primera (90-&gt;) R. ; Sunny (-&gt;90) L ; Sunny (90-&gt;) R ; Terrano (86-&gt;93) L ; Urvan (93-&gt;) L ; Vanette (90-&gt;96) R</li> <li>• <b>OPEL</b> Ascona (81-&gt;88) H ; Astra II (98-&gt;) R ; Calibra (90-&gt;) L +H ; Frontera (91-&gt;) L ; Omega A (86-&gt;94) L ; Omega B (94-&gt;) R ; Vectra A (88-&gt;95) L +H ; Vectra B (95-&gt;02) L</li> <li>• <b>RENAULT</b> R 19 (88-&gt;) H</li> <li>• <b>SEAT</b> Arosa (97-&gt;99) L ; Arosa (99-&gt;) R ; Cordoba (93-&gt;) R ; Ibiza (89-&gt;93) +H ; Ibiza (93-&gt;01) R. ; Leon (99-&gt;) R ; Toledo (98-&gt;) R</li> <li>• <b>SUBARU</b> Forester (97-&gt;) R ; Legacy (89-&gt;) R ; Vivio (92-&gt;) L</li> <li>• <b>SUZUKI</b> Alto (94-&gt;) L ; Grand Vitara (98-&gt;) L</li> <li>• <b>ŠKODA</b> Octavia (96-&gt;) R</li> <li>• <b>TOYOTA</b> Camry (91-&gt;00) R ; Camry (01-&gt;) R ; Celica (93-&gt;99) R ; Hiace (90-&gt;95) L ; Lexus GS300 (93-&gt;98) R ; Lexus IS200 (98-&gt;) R ; RAV 4 (00-&gt;) R</li> <li>• <b>VOLVO</b> 440, 460, 480 (86-&gt;96)</li> <li>• <b>VW</b> Corrado (88-&gt;96) L ; Golf III (91-&gt;97) R ; LT (82-&gt;96) L ; Lupo (98-&gt;) L ; Polo (94-&gt;99) L ; Polo (99-&gt;01) L ; Vento (91-&gt;) R.</li> </ul>
20" SPO-PCS-MS	510 MM	<ul style="list-style-type: none"> <li>• <b>AUDI</b> R ; TT (98-&gt;) R</li> <li>• <b>AZLK</b> Moskvitch - Aleko 2141 L</li> <li>• <b>BMW</b> Series 3 (82-&gt;91) L ; Series 3 (92-&gt;96) R ; Series 3 (97-&gt;) R ; Z3 (96-&gt;) L</li> <li>• <b>CHRYSLER</b> PT Cruiser (00-&gt;) L</li> <li>• <b>CITROËN</b> BX (82-&gt;) +H ; Saxo (96-&gt;) L ; Xantia (93-&gt;) R ; Xsara (97-&gt;) R ; XM (94-&gt;) R</li> <li>• <b>DAEWOO</b> Lublin II L ; Musso (96-&gt;) L ; Nubira (97-&gt;) L ; Polonez (94-&gt;) L +H</li> <li>• <b>DAIHATSU</b> Grand Move (96-&gt;) L ; Terios (97-&gt;) L</li> <li>• <b>FIAT</b> Croma (85-&gt;96) L ; Ducato (81-&gt;94) L ; Marea (96-&gt;) H</li> <li>• <b>FORD</b> Escort (90-&gt;98) L ; Maverick (93-&gt;99) R ; Mondeo (93-&gt;01) R +com.H ; Mondeo (01-&gt;) R ; Orion (90-&gt;93) L ; Probe (93-&gt;) L +H ; Scorpio (85-&gt;98) L +H ; Scorpio (93-&gt;) L ; Sierra (82-&gt;93) L +H ; Sierra combi () L ; Windstar (95-&gt;) R</li> <li>• <b>GAZ</b> Gazel 3302 L</li> <li>• <b>HONDA</b> CRX (92-&gt;01) L ; Civic (91-&gt;01) L ; Civic Aerodeck (98-&gt;) L ; HRV (98-&gt;) L ; Integra (98-&gt;) L ; Insight (00-&gt;) L ; Jazz (02-&gt;) L ; Logo (99-&gt;01) L</li> <li>• <b>HYUNDAI</b> Accent (94-&gt;) L +H ; Atos (97-&gt;) L ; H1 / H200 (99-&gt;) R ; Lantra / Elantra (95-&gt;) L ; Santa Fe (01-&gt;) R ; Sonata II (93-&gt;96) L ; Sonata III (96-&gt;98) L ; Sonata III (98-&gt;) R ; Terracan (02-&gt;) R ; XG (98-&gt;) R</li> <li>• <b>ISUZU</b> Trooper (92-&gt;) L</li> <li>• <b>JAGUAR</b> Sovereign (92-&gt;) L ; XJ s. IV (94-&gt;) L</li> <li>• <b>KIA</b> Magentis (01-&gt;) R ; Sportage (93-&gt;) L</li> </ul>

<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>20" SPO-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>510 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>LADA</b> Samara 2108 - 09 L ; Samara 2110 - 2112 ( ) L ; Oka 1111, 1113 ( )</li> <li>• <b>LANCIA</b> Delta (93-&gt;00) H ; Kappa (94-&gt;01) R ; Thema (84-&gt;94) L</li> <li>• <b>MAZ</b> Super L</li> <li>• <b>MAZDA</b> 121 (91-&gt;95) L ; 323 (94-&gt;98) H ; Demio (98-&gt;) L ; MPV (94-&gt;99) R ; MX6 (91-&gt;) L ; RX7 (87-&gt;96) L</li> <li>• <b>MERCEDES</b> 200D-280E (W123) (76-&gt;85) L ; Bus 207-410 (T1) (88-&gt;) L ; MB 100D (87-&gt;) L</li> <li>• <b>MITSUBISHI</b> 3000 GT (91-&gt;01) R ; Carisma (95-&gt;) R +H ; Colt / Mirage (88-&gt;95) L ; Eclipse (91-&gt; 95) L ; Eclipse (96-&gt;) H ; Lancer (92-&gt;95) L ; Pajero / Montero (00-&gt;) L ; Pajero Sport/Montero (98-&gt;) L</li> <li>• <b>NISSAN</b> 200 SX (88-&gt;94) L ; 200 SX (94-&gt;) R ; Almera Tino (00-&gt;) H ; Bluebird (86-&gt;94) L ; Maxima (88-&gt;95) L ; Micra (92-&gt;03) L ; Primera (90-&gt;) com.H ; Primera (99-&gt;01) R ; Sunny (90-&gt;) hatch.T ; Terrano II (93-&gt;96) R ; Terrano II (02-&gt;) R</li> <li>• <b>OPEL</b> Agila (00-&gt;) L ; Arena ( ) L ; Astra II (98-&gt;) L ; Combo (01-&gt;) L ; Corsa C (01-&gt;) L ; Monterey (92-&gt;) L ; Tigra (94-&gt;) H</li> <li>• <b>PEUGEOT</b> 106 (91-&gt;) L ; 306 (93-&gt;) R +H ; Expert (96-&gt;) R ; Express (82-&gt;94) L ; J5 (81-&gt;94) L</li> <li>• <b>RENAULT</b> Clio I (94-&gt;98) L ; Megane (96-&gt;02) R +com.H ; R 19 (88-&gt;) L ; R 21 (86-&gt;) L ; Trafic (89-&gt;00) L</li> <li>• <b>ROVER</b> 400 (95-&gt;00) L ; 45 (00-&gt;) L ; 600 (93-&gt;99) R ; 800 (91-&gt;99) L ; Maestro (83-&gt;94) L +H</li> <li>• <b>SAAB</b> 9-3 (98-&gt;) H ; 900 (87-&gt;93) H ; 900 (93-&gt;98) H ; 9000 (84-&gt;98) H</li> <li>• <b>SEAT</b> Toledo (91-&gt;98) L</li> <li>• <b>SUBARU</b> Legacy (99-&gt;) R ; SVX (91-&gt;97) R</li> <li>• <b>SUZUKI</b> Baleno (94-&gt;) L ; Swift (89-&gt;91) L ; Wagon R+ (97-&gt;) L</li> <li>• <b>ŠKODA</b> Favorit (93-&gt;95) L ; Felicia (94-&gt;) L ; Felicia pick-up (95-&gt;) L ; Forman (90-&gt;) L</li> <li>• <b>TOYOTA</b> Avensis (97-&gt;) com.H ; Camry (86-&gt;91) L ; Carina E (92-&gt;) com.H ; Carina II (87-&gt;92) L ; Celica (87-&gt;93) L ; Celica (93-&gt;99) H ; Corolla (87-&gt; 01) L ; Lexus GS300 (98-&gt;) R ; Paseo (95-&gt;) L ; RAV 4 (94-&gt;00) L ; Startlet (90-&gt;00) L ; Supra (89-&gt;95) L ; Supra (95-&gt;) R</li> <li>• <b>VOLVO</b> 440, 460, 480 (86-&gt;96) H ; 740, 760, 780 (83-&gt;95) L ; 940 (90-&gt;97) L ; S 40, V 40 (96-&gt;) R</li> <li>• <b>VW</b> Caddy (82-&gt;92) L ; Passat B5 (96-&gt;) R.</li> </ul>
<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>21" SPO-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>530 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>ALFA ROMEO</b> L ; Alfa 155 (92-&gt;96) L ; Alfa 156 (97-&gt;) R ; Alfa 164 (87-&gt;98) L ; Alfa 166 (98-&gt;) L</li> <li>• <b>AUDI</b> 80 / 90 (84-&gt;94) L ; 100 (82-&gt;90) L +H ; 200 (83-&gt;91) L +H ; Allroad Quattro (00-&gt;) R ; A 3 (96-&gt;) L ; A 4 (94-&gt;99) L ; A 4 (99-&gt;) R ; A 6 (94-&gt;) R ; A 8 (94-&gt;) R ; TT (98-&gt;) L</li> <li>• <b>BMW</b> Series 3 (92-&gt;96) L</li> <li>• <b>CHRYSLER</b> Neon (96-&gt;98) L ; PT Cruiser (00-&gt;) R</li> <li>• <b>DAEWOO</b> Matiz (98-&gt;) L</li> <li>• <b>DAIHATSU</b> YRV (01-&gt;) L</li> <li>• <b>FORD</b> Maverick (93-&gt;99) L ; Mondeo (93-&gt;01) L</li> <li>• <b>HONDA</b> CRX (01-&gt;) L ; Legend (91-&gt;) L ; Prelude (91-&gt;) L</li> <li>• <b>HYUNDAI</b> Lantra / Elantra (90-&gt;95) L ; Sonata I (88-&gt;93) L</li> <li>• <b>JAGUAR</b> Sovereign (86-&gt;93) ; XJ6 (86-&gt;) ; XK8 (96-&gt;) L</li> <li>• <b>KIA</b> Clarus (96-&gt;) L ; K2700 ( ) L ; Leo (96-&gt;) L ; Pregio (98-&gt;) L ; Rio (00-&gt;) L ; Sephia / Sephia II (93-&gt;) L ; Shuma / Shuma II (97-&gt;) L</li> <li>• <b>LANCIA</b> Delta (93-&gt;00) L ; Lybra (99-&gt;) R</li> <li>• <b>MAZDA</b> 323 (94-&gt;98) L ; 323 (97-&gt;) L ; 323C / F / P / S (89-&gt;94) L ; 626 (91-&gt;97) L ; 626 (97-&gt;01) L +H ; MX3 (91-&gt;) L +H ; Xedos 6 (92-&gt;) L ; Xedos 9 (93-&gt;) L</li> <li>• <b>MERCEDES</b> Sprinter (95-&gt;) R</li> <li>• <b>MITSUBISHI</b> 3000 GT (91-&gt;01) L ; Carisma (95-&gt;) L ; Colt / Mirage (95-&gt;) L ; Eclipse (96-&gt;) R ; Galant (92-&gt;97) L ; Lancer (95-&gt;) L ; Sigma (90-&gt;) L ; Space Star (98-&gt;) L</li> <li>• <b>NISSAN</b> 200 SX (94-&gt;) L ; Almera (95-&gt;00) L ; Maxima QX (94-&gt; 00) R ; Micra (03-&gt;) L ; Pathfinder (98-&gt;) R ; Primera (90-&gt;) L ; Primera (99-&gt;01) L +com.H ; Sunny (90-&gt;) L ; Terrano II (93-&gt;96) L ; Terrano II (97-&gt;01) R ; Terrano II (02-&gt;) L</li> <li>• <b>OPEL</b> Vivaro (01-&gt;) R</li> <li>• <b>RENAULT</b> Clio II / Clio III (98-&gt;) L ; Kangoo (97-&gt;) L ; Trafic (01-&gt;) R</li> <li>• <b>ROVER</b> Freelander (97-&gt;) L</li> <li>• <b>SAAB</b> 9-3 (98-&gt;) L ; 900 (93-&gt;98) L ; 9000 (84-&gt;98) L</li> <li>• <b>SEAT</b> Arosa (99-&gt;) L ; Cordoba (93-&gt;) L ; Ibiza (93-&gt;01) L ; Inca (95-&gt;) L ; Leon (99-&gt;) L ; Toledo (98-&gt;) L</li> <li>• <b>SUBARU</b> Forester (97-&gt;) L ; Impreza (92-&gt;) L ; Legacy (89-&gt;) L</li> <li>• <b>SUZUKI</b> Swift (92-&gt;) L</li> <li>• <b>ŠKODA</b> Fabia (00-&gt;) L ; Octavia (96-&gt;) L</li> <li>• <b>TOYOTA</b> Avensis (97-&gt;) L ; Camry (91-&gt;00) L ; Carina E (92-&gt;) L ; Celica (93-&gt;99) L ; Hiace (95-&gt;) L ; Lexus GS300 (93-&gt;98) L ; Supra (95-&gt;) L ; Yaris (99-&gt;) L</li> <li>• <b>VOLVO</b> 440, 460, 480 (86-&gt;96) L ; 850 (91-&gt;98) L ; 960 (90-&gt;97) L ; C 70, S 70, V 70 (97-&gt;) L ; S 40, V 40 (96-&gt;) L ; S 90, V 90 (96-&gt;98) L</li> <li>• <b>VW</b> Bora (98-&gt;) L ; Caddy (95-&gt;) L ; Golf III (91-&gt;97) L ; Golf IV (97-&gt;) L ; LT (96-&gt;) R ; Passat (88-&gt;97) L ; Passat B5 (96-&gt;) L ; Polo Classic (95-&gt;99) L ; Polo Classic (99-&gt;02) L ; Transporter T4 (90-&gt;) L ; Vento (91-&gt;) L</li> <li>• <b>ZAZ</b> Tavria (88-&gt;)</li> </ul>
<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>19" BUS-PCS-MS</b></p>	<p style="writing-mode: vertical-rl; transform: rotate(180deg);"><b>480 MM</b></p>	<ul style="list-style-type: none"> <li>• <b>KAMAZ</b> (-&gt; 98) ; (98-&gt;)</li> <li>• <b>KIA</b> K2700 (98-&gt;) R ; Pregio (98-&gt;) R</li> <li>• <b>VW</b> LT (82 - 96)</li> </ul>

<b>20"BUS- PCS-MS</b>	<b>500 MM</b>	<ul style="list-style-type: none"> <li>• <b>DAEWOO</b> LUBLIN II (-&gt;98)</li> <li>• <b>FIAT</b> DUCATO (81 - 94)</li> <li>• <b>FORD</b> TOURNEO (90 - 93)</li> <li>• <b>HYUNDAI</b> H1 (99 -&gt;) R ; H200 (99 -&gt;) R</li> <li>• <b>JELCZ</b> s. 300; 400; 600 (74 -&gt;)</li> <li>• <b>LDV</b> (96 -&gt;)</li> <li>• <b>MAN</b> 6.90F - 10.150FK (79 - 94) ; L 2000 (92 -&gt;)</li> <li>• <b>MERCEDES</b> MB 100 (80 - 89) ; T1 207 - 410 (77 - 95)</li> <li>• <b>MITSUBISHI</b> CANTER (98 -&gt;)</li> <li>• <b>PEUGEOT</b> J5 (81 - 93)</li> <li>• <b>RENAULT</b> MAJOR (81 -&gt;)</li> <li>• <b>STAR</b> 8125; 12155 (99 - 00) ; S200;S28;S29;S1142 (-&gt; 99) ; S2000 (00 -&gt;)</li> <li>• <b>STEYR</b> 591 - 891 (78 - 86) ; 8 S - 17 S (86 -&gt;)</li> </ul>
<b>21"BUS- PCS-MS</b>	<b>525 MM</b>	<ul style="list-style-type: none"> <li>• <b>KIA</b> K2700 (98-&gt;) L ; Pregio (98-&gt;) L</li> </ul>
<b>22"BUS- PCS-MS</b>	<b>550 MM</b>	<ul style="list-style-type: none"> <li>• <b>CITROËN</b> BERLINGO (96-&gt;) ; JUMPER (94-&gt;)</li> <li>• <b>DAEWOO</b> LUBLIN 3 (98-&gt;)</li> <li>• <b>DAF</b> 95 XF (91-&gt;) ; LF (00-&gt;)</li> <li>• <b>FIAT</b> DUCATO (94-&gt;)</li> <li>• <b>FORD</b> TOURNEO (94 - 00) ; TRANSIT (85 - 94) ; TRANSIT (94 - 00)</li> <li>• <b>IVECO</b> DAILY (78-&gt;)</li> <li>• <b>MERCEDES</b> SPRINTER (95-&gt;) R</li> <li>• <b>PEUGEOT</b> BOXER (94-&gt;) ; PARTNER (96-&gt;)</li> <li>• <b>TATRA</b></li> </ul>
<b>23"BUS- PCS-MS</b>	<b>575 MM</b>	
<b>24"BUS- PCS-MS</b>	<b>600 MM</b>	<ul style="list-style-type: none"> <li>• <b>DAF</b> 65; 75; 85 (92-&gt;)</li> <li>• <b>FORD</b> TOURNEO (00-&gt;) R ; TRANSIT (00-&gt;) R</li> <li>• <b>IVECO</b> DAILY (00 - 02)</li> <li>• <b>MAN</b> F 2000 (96-&gt;) ; F 9019.242 - 48.462 (86 - 96) ; M 2000 (96-&gt;) ; M 9012.152 - 17.232 (88 - 96)</li> <li>• <b>MERCEDES</b> LK 709 - 1520 (86-&gt;) ; SPRINTER (95-&gt;) L ; T2 507 - 817 (86-&gt;) ; VARIO (96-&gt;)</li> <li>• <b>RENAULT</b> MASTER (89 - 98) ; MESSENGER (90-&gt;) ; MIDLINER (89-&gt;)</li> <li>• <b>SCANIA</b> 92; 112; 142 (80 - 88) ; 93; 113; 143 (88 - 96)</li> <li>• <b>VOLVO</b> F7; F10; F12; F16 (75 - 94)</li> <li>• <b>VW</b> LT (96-&gt;)</li> </ul>
<b>26"BUS- PCS-MS</b>	<b>650 MM</b>	<ul style="list-style-type: none"> <li>• <b>HYUNDAI</b> H1 (99-&gt;) L ; H200 (99-&gt;) L</li> <li>• <b>IVECO</b> EURO CARGO (91-&gt;) ; EURO STAR (92-&gt;) ; EURO TECH (91-&gt;) ; EURO TRAKKER (93-&gt;)</li> <li>• <b>MERCEDES</b> ATEGO (98-&gt;) ; MK 1222 - 3233 (88-&gt;) ; SK 1729 - 4850 (88-&gt;)</li> <li>• <b>VOLVO</b> FH12; FH16 (93-&gt;) ; FM7; FM12 (98-&gt;)</li> </ul>

<b>28"BUS- PCS-MS</b>	<b>700 MM</b>	<ul style="list-style-type: none"> <li>• <b>FORD</b> TOURNEO (00-&gt;) L ; TRANSIT (00-&gt;) L</li> <li>• <b>MERCEDES</b> ACTROS (96-&gt;)</li> <li>• <b>RENAULT</b> MAGNUM (90 - 97) ; MAGNUM (97-&gt;)</li> <li>• <b>SCANIA</b> 94; 114; 124; 144 (96-&gt;)</li> <li>• <b>VOLVO</b> FL7; FL10 (85 - 94) ; FL7; FL10; FL12 (95-&gt;)</li> </ul>
<b>32"BUS- PCS-MS</b>	<b>800 MM</b>	<ul style="list-style-type: none"> <li>• <b>DRÖGMÖLLER</b> E 420; E 440 (80-&gt;)</li> <li>• <b>JELCZ</b> M121M / M181M</li> <li>• <b>KÄSSBOHRER</b> Setra S 215 HDH Intercont (85 - 96) ; Setra S 215 HDS (80 - 83) ; Setra S 216 HDS (80 - 96) ; Setra S 228 DT (82 - 96)</li> <li>• <b>MAN</b> MG 113 ; SG-Serie 242; SL II 202 (84 - 94)</li> <li>• <b>MERCEDES-BENZ</b> O 402 (86-&gt;) ; O 405; E; G (Ü 80) (84-&gt;)</li> <li>• <b>NEOPLAN</b> Cityliner N 116 (85-&gt;) ; Clubliner N 122 (86 - 89) ; Jumbocruiser N 138 (86 - 96) ; SL II (81 - 96) ; Skyliner N 122 (86-&gt;) ; Solaris ; Spaceliner N 117 (86 - 96)</li> </ul>
<b>36"BUS- PCS-MS</b>	<b>900 MM</b>	<ul style="list-style-type: none"> <li>• <b>KÄSSBOHRER</b> Setra S 228 DT (82 - 96)</li> <li>• <b>MAN</b> NL-Serie NL 202 (89 - 94)</li> <li>• <b>MERCEDES-BENZ</b> O 303 (79 - 92) ; O 405; E; G (Ü 80) (89-&gt;) ; O 405; GN; N (Ü 80) (89-&gt;)</li> </ul>
<b>40"BUS- PCS-MS</b>	<b>1000 MM</b>	<ul style="list-style-type: none"> <li>• <b>DRÖGMÖLLER</b> E 290; E 300; E 310; E 320; E 330; E 430 (80-&gt;)</li> <li>• <b>HEULIEZ</b> GX 77 H (90-&gt;)</li> <li>• <b>IVECO</b> 380.10.29 (92-&gt;) ; 380.12.35; 380.12.38 (93-&gt;) ; EuroClass (93-&gt;) ; M 2000 (82 - 84)</li> <li>• <b>KÄSSBOHRER</b> Setra S 208/209; H (79 - 83) ; Setra S 210/211 H (80 - 96) ; Setra S 212; 213 H /HR/RL (79 - 96); Setra S 214HD; 215; H (80 - 96) ; Setra S 215 HDH Intercont (85 - 96) ; Setra S 215 HDS (80 - 83) ; Setra S 215 HR; RL; SL; UL (79 - 96) ; Setra S 216 HDS (80 - 96) ; Setra S 300 N (92-&gt;) ; Setra SG 219 SL; 221 UL (84-&gt;)</li> <li>• <b>MAN</b> SG-Serie 220/240 H; HÜ (80 - 86) ; SR 240/280/321/361 (78 - 86) ; SÜ 240 (78 - 83)</li> <li>• <b>MERCEDES-BENZ</b> O 303 LHD (87 - 92) ; O 303 RHD (85 - 92) ; O 303 (79 - 92) ; O 407 (87-&gt;) ; O 408 (91-&gt;)</li> <li>• <b>NEOPLAN</b> Clubliner N 122 (81 - 89) ; Combiiner N 316 (85 - 92) ; Jetliner N 208; 212; 213; 214; 216 (81-&gt;) ; Jum bocruiser N 138 (83 - 96) ; Spaceliner N117; N119 (86 - 96) ; Transliner N 316 (89 - 91)</li> <li>• <b>ORLANDI</b> Domino GT 370 S 12.30 (88-&gt;)</li> <li>• <b>RENAULT</b> Agora (98-&gt;) ; FR 1 (82 - 96) ; LLIADÉ GT/ GTC/ GTE/ GTX/ GTXE/ RT/ TEX/ RT/ RTC/ TE/ TEC (97-&gt;) ; R 312 (86-&gt;)</li> <li>• <b>SCANIA</b> 82 G; 82 P; 82 T (80 - 88)</li> <li>• <b>VOLVO</b> C 10 (84 - 87)</li> </ul>

Ihr Handelsvertreter - Your distributor  
Ваш дистрибьютор - Wasz przedstawiciel handlowy



**MS**<sup>®</sup>  
**AUTOMOBILTECHNIK**  
**GERMANY**

**MASTER-SPORT-Automobiltechnik (MS) GmbH**  
Leopoldstrasse 244, 80807 München, Deutschland  
[www.master-sport.de](http://www.master-sport.de)